

Fireplace is rusted out around damper, recommend not using, potential hazard



Rust hold around damper.



Rusted out around damper

