


If you are getting loud noises from your pellet stove, the solution could be very simple


- 1- First of all, get into the back of the stove, unscrew the 6x size8 screws and remove the bottom grill.



- 2- You will see the combex fan in the lower section of the stove.




Between the two venting assemblys is the motor.




- 3- Usually the problematic models are the A.O Smith fans, they have little black fins that cool down the motor and these little fins can move and end up hitting the venting assembly, causing the noise.






- 4- Insert a screw driver between the motor and the fan to separate the venting fins from the venting assembly by about $\frac{1}{4}$ in





This should resolve your noise problem!

If you have the other model, it's the same procedure, except there is a little Allan screw witch has to be loosen before moving the fins.



If there is still noise after this, contact your retailer.