Weld on baffle bottom, purpose unknown at this time.

> Baffle pin placement changed. Old placement hole still in place.