

## Modification #1: Allow Inlet damper to open fully


Front schematic of VC Defiant Flexburn






Shim the inlet so damper opens fully Old defiant damper was external opening New VC Flexburn damper opens in

## Modification #2:Controlled small underfire air damper



Users report cracking ash door open But it's a large crack when it opens



Obstructed

Damper

This style of damper on many DIY wood stoves

Install a controllable damper in ash pan